




R5000 Overall dimensions diagram									
Progress				Weight		proportion			
						1:1			